

FIRE: Singapore



FIRE: Singapore



FIRE: Prior to sinking



FIRE: Singapore 30th May 2022



31st May

– after fire & prior to sinking in Marina



Salvaged remains being lifted from barge for disposal



Marina clean-up completed



FIRE MALAYSIA “Remains of motor yacht which caught on fire and sank”



FIRE: Thailand



GROUNDING: Indonesia



GROUNDING:

Prop-shaft 'I' bracket pushed through hull, vessel flooded



GROUNDING: Re-floated. Yacht eventually CTL



GROUNDING:

Thailand, after another vessel dragged anchor



GROUNDING



GROUNDING



Vessel “safely” anchored



Vessel (arrowed) sometime later, after vessel swung onto reef during tide change



Sheered prop-shaft after moving ahead when prop was on reef



SINKING: Indonesia



SINKING



COLLISION WITH SHIP





COLLISION



COLLISION

(Catamaran hulls frequently vertically delaminate at the stem)



COLLISION



COLLISION



GROUNDING damage



GROUNDING

- extensive damage requires replacement prop



UNSEAWORTHINESS



UNSEAWORTHINESS

– Rotted timber



AN UNHAPPY SHIP



COMPLEX SPEED & ANGLE OF BLOW :)



COLLISION - SINGAPORE STRAITS

COMPLEX SPEED & ANGLE OF BLOW

The smaller ship,
crossing the Singapore
Traffic Separation Zone,
was the give-way ship &
altered to starboard.

The large ship altered to
port....





DISASTERS DO HAPPEN

CONTAINER STOW COLLAPSE, GROUNDINGS



COLLISIONS, GROUNDINGS, CAPSIZE, OIL-SPILL